

CCTV REPORT

CLIENT: CSL Surveys

JOB NO: 14230

PROJECT: Police Headquarters
Stanborough
Welwyn Garden City
AL8 6PH

DATE: October 2020

REVISION: -



INSTRUCTIONS FOR VIEWING REPORT

VIEWING VIDEO CLIPS

Please ensure that the Video viewing software is able to play 'MPEG Layer-4 Audio File (MP4)' type. We recommend to use 'Windows Media Player' for Microsoft operating systems and 'Quick Time Player' for Apple Mac operating systems. We recommend to check that the file type: 'MPEG Layer-4 Audio' is enabled within the settings.

NAVIGATING THE PDF REPORT

For this you will require 'ADOBE READER 6' or later version

The CCTV PDF file can be run direct from the disc

In each section of the report the text for DRAWING, REPORT, VIDEO or IMAGE (if relevant) is a toggle switch between the various details, so by clicking the mouse arrow on the text it will navigate to the section of the report that the text represents.



DEFECT GRADE DESCRIPTIONS

- 0 **NO DEFECT** Drainage feature eg. Junction, line change, manhole.
No action required.
- 1 **VERY MINOR DEFECT** eg. Attached / Settled Deposits 5% - 15%.
No action required.
- 2 **MINOR DEFECT** Observed defect does not appear to be currently causing an issue with the function of the drain run. Defect may worsen if not appropriately maintained and monitored. No immediate action required.
- 3 **MEDIUM DEFECT** Observed defect does not appear to be currently causing an issue with the function of the drain run. Defect may worsen if not appropriately maintained and monitored. No immediate action required.
- 4 **MAJOR DEFECT** Observed defect is causing a significant issue with the function of the drain run. Immediate action is required to maintain the function of the drain run and prevent the defect from worsening.
- 5 **MAJOR DEFECT** Observed defect has caused the drain run to cease functioning. Immediate action is required.


The above Defect Grade Descriptions are for advisory purposes only.

CCTV SURVEY DISCLAIMER

Amethyst Surveys has made every effort available to produce a high quality and in-depth survey, outlining all significant observations and where appropriate, relative remedial actions. We cannot, however, accept any liability for any misinterpretation by third parties in relation to the information contained herein. Also we cannot accept any liability for any change in invert levels recorded on site if the land detail changes from the date of this survey. The condition of the drains shown within this report are a representation of the areas surveyed on the date(s) of this report only.

The CCTV camera unit chainage is calibrated before each survey. However, we cannot guarantee or accept liability that the recording of the chainage is exact and therefore recommend that all distance measurements are treated as approximate.





NOTES:

NAVIGATION KEY

CCTV KEY

- R1** RED CCTV RUN NUMBER DENOTES MAJOR FAULT
- R2** AMBER CCTV RUN NUMBER DENOTES MINOR FAULT
- R3** GREEN CCTV RUN NUMBER DENOTES NO FAULTS

UTILITY KEY

- FOUL WATER SEWER
- SURFACE WATER SEWER
- COMBINED WATER SEWER
- CONTAMINATED SURFACE
- UNIDENTIFIED SEWER
- PUMPING MAIN
- SERVICE DUCT
- TRENCH SCAR
- SURVEY BOUNDARY

ABBREVIATIONS

AC ASBESTOS CEMENT	LP LAMP POST
AR ASSUMED ROUTE	MH MANHOLE
BB BASE BEND	MW MONITORING WELL
BD BACKDROP	OH OVERHEAD
BH BOREHOLE	OSA OFF SURVEY AREA
BR BRICK	PE POLYETHYLENE
BT BT INSPECTION CHAMBER	PL PLASTIC
CATV CATV INSPECTION CHAMBER	PR PIPE RISER
CBX CONTROL BOX	PVC POLYVINYL CHLORIDE
CI CAST IRON	RE RODDING EYE
CL COVER LEVEL	RWP RAIN WATER PIPE
CR CABLE RISER	SIA SOAKAWAY
CP CATCHPIT	SI SPIRUP IRON
d DEPTH	ST STOP TAP
DI DUCTILE IRON	S.T STEEL
DP DOWN PIPE	SV SLUICE VALVE
ED EMPTY DUCT	SVP SOIL VENT PIPE
EOSC END OF TRENCH SCAR	TE TRAPPED EXT
EOT END OF TRACE	TFR TAKEN FROM RECORD
ER EARTHING ROD	TL TRAFFIC LIGHT
EP ELECTRICITY POLE	TP TELEGRAPH POLE
FH FIRE HYDRANT	UTCCVT UNABLE TO CCTV
FL FLOOD LIGHT	UTF UNABLE TO FIND
G GULLY	UTL UNABLE TO LIFT
GPR GROUND PENETRATING RADAR	UTS UNABLE TO SURVEY
GRP GLASS REINFORCED PLASTIC	VC VITRIFIED CLAY
GV GAS VALVE	VP VENT PIPE
HL HIGH LEVEL	VR VAPOUR RECOVERY
HOR HEAD OF RUN	WL WATER LEVEL
IC INSPECTION CHAMBER	WM WATER METER
IL INVERT LEVEL	WO WASH OUT VALVE
SWS SURFACE WATER SEWER	
CWS COMBINED WATER SEWER	

DISCLAIMER

ELECTROMAGNETIC TECHNIQUES AND/OR GROUND PENETRATING RADAR HAVE BEEN USED IN THE LOCATION OF UNDERGROUND SERVICES. THE RESULTS ARE NOT INFALLIBLE AND TRIAL EXCAVATIONS SHOULD BE CARRIED OUT TO CONFIRM SERVICE IDENTIFICATION. POSITIONS AND PARTICULARLY DEPTHS, WHERE THESE ARE CRITICAL, ALTHOUGH ALL REASONABLE EFFORT HAS BEEN MADE IN SEARCHING AVAILABLE RECORD DRAWINGS, THE COMPLETENESS OF THE UNDERGROUND SERVICES INFORMATION CANNOT BE GUARANTEED. THE METHODS OF SURVEY DOES NOT DIFFERENTIATE BETWEEN LIVE AND DEAD SERVICES AND AS SUCH ALL SERVICES SHOULD BE TREATED AS LIVE. WHERE SERVICES ARE NON-METALLIC POSITIONS MAY BE TAKEN FROM RECORDS, TRENCH SCARS & SURFACE DETAIL. WHERE QUOTED, DEPTH ESTIMATIONS ARE GENERALLY TO THE CENTRE OF THE SERVICE, DEPTHS TO GRAVITY SEWERS AND DRAINS ARE GENERALLY TO INVERT LEVELS UNLESS OTHERWISE STATED. PIPE SIZES WHICH CANNOT BE OBTAINED BY VISUAL SURVEY ARE TAKEN FROM RECORD DRAWINGS OR MARKER PLATES WHERE AVAILABLE. WHERE GROUND PENETRATING RADAR HAS BEEN USED IT WILL PRIMARILY HAVE BEEN TO IDENTIFY UNDERGROUND UTILITIES. IF POSSIBLE WE WILL ALSO IDENTIFY UNDERGROUND STRUCTURES/ TANKS ETC. BUT CANNOT GUARANTEE TO HAVE LOCATED ALL SUCH ITEMS. THE USE OF RADAR CAN BE LIMITED BOTH BY SURFACE CONDITIONS AND ALSO BY SOIL TYPE. DEPTH ESTIMATES WOULD NOT NORMALLY BE PROVIDED FOR SERVICES LOCATED WITH GPR.

REV	DATE	COMMENT	CAD

CLIENT: **Vincent and Gorbng Limited**

PROJECT: **Police HQ
Stanborough
Welwyn Garden City
AL8 6XF**


TITLE: **Underground
CCTV Drainage Survey**

AMETHYST SURVEYS LIMITED

Unit 6a Davy Court, Central Park
Rugby, Warwickshire, CV23 0UZ
Tel: 01788 566740
Fax: 01788 571158
Email: enquiries@amethystsurveys.com
www.amethystsurveys.com

DATE: 12.10.20	JOB No: 14230
DRAWING No: 14230_CCTV_1	REV: 0
DRAWN: DOT	SURVEYED: AS
APPROVED: TPD	SCALE: 1:200 @AO





NOTES:

NAVIGATION KEY

CCTV KEY

- R1** RED CCTV RUN NUMBER DENOTES MAJOR FAULT
- R2** AMBER CCTV RUN NUMBER DENOTES MINOR FAULT
- R3** GREEN CCTV RUN NUMBER DENOTES NO FAULTS

UTILITY KEY

- FOUL WATER SEWER
- SURFACE WATER SEWER
- COMBINED WATER SEWER
- CONTAMINATED SURFACE
- UNIDENTIFIED SEWER
- PUMPING MAIN
- SERVICE DUCT
- TRENCH SCAR
- SURVEY BOUNDARY

CABLE / PIPE RISER END OF TRACE
 BACKDROP / TRAPPED EXIT HEAD OF RUN / CAPPED
 DRAINAGE VALVE PIPE INLET / OUTFALL

ABBREVIATIONS

AC	ASBESTOS CEMENT	LP	LAMP POST
AR	ASSUMED ROUTE	MH	MANHOLE
BB	BASE BEND	MW	MONITORING WELL
BD	BACKDROP	OH	OVERHEAD
BH	BOREHOLE	OSA	OFF SURVEY AREA
BR	BRICK	PE	POLYETHYLENE PLASTIC
BT	BT INSPECTION CHAMBER	PL	PIPE
CATV	CATV INSPECTION CHAMBER	PR	PIPE RISER
CBX	CONTROL BOX	PVC	POLYVINYL CHLORIDE
CI	CAST IRON	RE	RODDING EYE
CL	COVER LEVEL	RWP	RAIN WATER PIPE
CR	CABLE RISER	SIA	SOAKAWAY
CP	CATCHPIT	SR	SPUN IRON
d	DEPTH	ST	STOP TAP
DI	DUCTILE IRON	S.T	STEEL
DP	DOWN PIPE	SV	SLUICE VALVE
ED	EMPTY DUCT	SVP	SOIL VENT PIPE
EOSC	END OF TRENCH SCAR	TE	TRAPPED EXIT
EOT	END OF TRACE	TFR	TAKEN FROM RECORD
ER	EARTHING ROD	TL	TRAFFIC LIGHT
EP	ELECTRICITY POLE	TP	TELEGRAPH POLE
FH	FIRE HYDRANT	UT/CCTV	UNABLE TO CCTV
FL	FLOOD LIGHT	UTF	UNABLE TO FIND
G	GULLY	UTL	UNABLE TO LIFT
GPR	GROUND PENETRATING RADAR	UTS	UNABLE TO SURVEY
GRP	GLASS REINFORCED PLASTIC	VC	VITRIFIED CLAY
GV	GAS VALVE	VP	VENT PIPE
HL	HIGH LEVEL	VR	VAPOUR RECOVERY
HOR	HEAD OF RUN	WL	WATER LEVEL
IC	INSPECTION CHAMBER	WM	WATER METER
IL	INVERT LEVEL	WO	WASH OUT VALVE
SWS	SURFACE WATER SEWER		
CSWS	CONTAMINATED SURFACE WATER SEWER		
FWS	FOUL WATER SEWER		
CWS	COMBINED WATER SEWER		

DISCLAIMER

ELECTRO-MAGNETIC TECHNIQUES AND/OR GROUND PENETRATING RADAR HAVE BEEN USED IN THE LOCATION OF UNDERGROUND SERVICES. THE RESULTS ARE NOT INFALLIBLE AND TRIAL EXCAVATIONS SHOULD BE CARRIED OUT TO CONFIRM SERVICE IDENTIFICATION, POSITIONS AND PARTICULARLY DEPTHS, WHERE THESE ARE CRITICAL. ALTHOUGH ALL REASONABLE EFFORT HAS BEEN MADE IN SEARCHING AVAILABLE RECORD DRAWINGS, THE COMPLETENESS OF THE UNDERGROUND SERVICES INFORMATION CANNOT BE GUARANTEED. THE METHODS OF SURVEY DOES NOT DIFFERENTIATE BETWEEN LIVE AND DEAD SERVICES AND AS SUCH ALL SERVICES SHOULD BE TREATED AS LIVE. WHERE SERVICES ARE NON-METALLIC POSITIONS MAY BE TAKEN FROM RECORDS, TRENCH SCARS & SURFACE DETAIL. WHERE QUOTED, DEPTH ESTIMATIONS ARE GENERALLY TO THE CENTRE OF THE SERVICE. DEPTHS TO GRAVITY SEWERS AND DRAINS ARE GENERALLY TO INVERT LEVELS UNLESS OTHERWISE STATED. PIPE SIZES WHICH CANNOT BE OBTAINED BY VISUAL SURVEY ARE TAKEN FROM RECORD DRAWINGS OR MARKER PLATES WHERE AVAILABLE. WHERE GROUND PENETRATING RADAR HAS BEEN USED IT WILL PRIMARILY HAVE BEEN TO IDENTIFY UNDERGROUND UTILITIES IF POSSIBLE WE WILL ALSO IDENTIFY UNDERGROUND STRUCTURES/ TANKS ETC. BUT CANNOT GUARANTEE TO HAVE LOCATED ALL SUCH ITEMS. THE USE OF RADAR CAN BE LIMITED BOTH BY SURFACE CONDITIONS AND ALSO BY SOIL TYPE. DEPTH ESTIMATES WOULD NOT NORMALLY BE PROVIDED FOR SERVICES LOCATED WITH GPR.

REV	DATE	COMMENT	CAD

CLIENT: Vincent and Goring Limited


PROJECT: Police HQ
Stanborough
Welwyn Garden City
AL8 6XF

TITLE: Underground
CCTV Drainage Survey


AMETHYST SURVEYS LIMITED

Unit 6a Davy Court, Central Park
Rugby, Warwickshire, CV23 0UZ
Tel: 01788 566740
Fax: 01788 571158
Email: enquiries@amethystsurveys.com
www.amethystsurveys.com

DATE: 12.10.20	JOB No: 14230
DRAWING No: 14230_CCTV_2	REV: 0
DRAWN: DOT	SURVEYED: AS
APPROVED: TPD	SCALE: 1:200 @A0



NOTES:



- CCTV KEY**
- R1** RED CCTV RUN NUMBER DENOTES MAJOR FAULT
 - R2** AMBER CCTV RUN NUMBER DENOTES MINOR FAULT
 - R3** GREEN CCTV RUN NUMBER DENOTES NO FAULTS

- UTILITY KEY**
- FOUL WATER SEWER
 - SURFACE WATER SEWER
 - COMBINED WATER SEWER
 - CONTAMINATED SURFACE
 - UNIDENTIFIED SEWER
 - PUMPING MAIN
 - SERVICE DUCT
 - TRENCH SCAR
 - SURVEY BOUNDARY
 - CABLE / PIPE RISER
 - BACKDROP / TRAPPED EXIT
 - DRAINAGE VALVE
 - END OF TRACE
 - HEAD OF RUN / CAPPED
 - PIPE INLET / OUTFALL

ABBREVIATIONS

AC	ASBESTOS CEMENT	LP	LAMP POST
AR	ASSUMED ROUTE	MH	MANHOLE
BB	BASE BEND	MW	MONITORING WELL
BD	BACKDROP	OH	OVERHEAD
BH	BOREHOLE	OSA	OFF SURVEY AREA
BR	BRICK	PE	POLYETHYLENE
BT	BT INSPECTION CHAMBER	PL	PLASTIC
CATV	CATV INSPECTION CHAMBER	PR	PIPE RISER
CBX	CONTROL BOX	PVC	POLYVINYL CHLORIDE
CI	CAST IRON	RE	RODDING EYE
CL	COVER LEVEL	RWP	RAIN WATER PIPE
CR	CABLE RISER	SIA	SOAKAWAY
CP	CATCHPIT	SI	SPUN IRON
d	DEPTH	ST	STOP TAP
DI	DUCTILE IRON	S.T	STEEL
DP	DOWN PIPE	SV	SLUICE VALVE
ED	EMPTY DUCT	SVP	SOIL VENT PIPE
EOSC	END OF TRENCH SCAR	TE	TRAPPED EXIT
EOT	END OF TRACE	TFR	TAKEN FROM RECORD
ER	EARTHING ROD	TL	TRAFFIC LIGHT
EP	ELECTRICITY POLE	TP	TELEGRAPH POLE
FH	FIRE HYDRANT	UTCCTV	UNABLE TO CCTV
FL	FLOOD LIGHT	UTF	UNABLE TO FIND
G	GULLY	UTL	UNABLE TO LIFT
GPR	GROUND PENETRATING RADAR	UTS	UNABLE TO SURVEY
GRP	GLASS REINFORCED PLASTIC	VC	VITRIFIED CLAY
GV	GAS VALVE	VP	VENT PIPE
HL	HIGH LEVEL	VR	VAPOUR RECOVERY
HOR	HEAD OF RUN	WL	WATER LEVEL
IC	INSPECTION CHAMBER	WM	WATER METER
IL	INVERT LEVEL	WO	WASH OUT VALVE
SWS	SURFACE WATER SEWER		
CSWS	CONTAMINATED SURFACE WATER SEWER		
FWS	FOUL WATER SEWER		
CWS	COMBINED WATER SEWER		

DISCLAIMER

ELECTROMAGNETIC TECHNIQUES AND/OR GROUND PENETRATING RADAR HAVE BEEN USED IN THE LOCATION OF UNDERGROUND SERVICES. THE RESULTS ARE NOT INFALLIBLE AND TRIAL EXCAVATIONS SHOULD BE CARRIED OUT TO CONFIRM SERVICE IDENTIFICATION, POSITIONS AND PARTICULARLY DEPTHS, WHERE THESE ARE CRITICAL. ALTHOUGH ALL REASONABLE EFFORT HAS BEEN MADE IN SEARCHING AVAILABLE RECORD DRAWINGS, THE COMPLETENESS OF THE UNDERGROUND SERVICES INFORMATION CANNOT BE GUARANTEED. THE METHODS OF SURVEY DOES NOT DIFFERENTIATE BETWEEN LIVE AND DEAD SERVICES AND AS SUCH ALL SERVICES SHOULD BE TREATED AS LIVE. WHERE SERVICES ARE NON-METALLIC POSITIONS MAY BE TAKEN FROM RECORDS, TRENCH SCARS & SURFACE DETAIL. WHERE QUOTED, DEPTH ESTIMATIONS ARE GENERALLY TO THE CENTRE OF THE SERVICE. DEPTHS TO GRAVITY SEWERS AND DRAINS ARE GENERALLY TO INVERT LEVELS UNLESS OTHERWISE STATED. PIPE SIZES WHICH CANNOT BE OBTAINED BY VISUAL SURVEY ARE TAKEN FROM RECORD DRAWINGS OR MARKER PLATES WHERE AVAILABLE. WHERE GROUND PENETRATING RADAR HAS BEEN USED IT WILL PRIMARILY HAVE BEEN TO IDENTIFY UNDERGROUND UTILITIES IF POSSIBLE WE WILL ALSO IDENTIFY UNDERGROUND STRUCTURES/ TANKS ETC. BUT CANNOT GUARANTEE TO HAVE LOCATED ALL SUCH ITEMS. THE USE OF RADAR CAN BE LIMITED BOTH BY SURFACE CONDITIONS AND ALSO BY SOIL TYPE. DEPTH ESTIMATES WOULD NOT NORMALLY BE PROVIDED FOR SERVICES LOCATED WITH GPR.

REV	DATE	COMMENT	CAD

CLIENT: Vincent and Goring Limited

PROJECT: Police HQ
Stanborough
Welwyn Garden City
AL8 6XF

TITLE: Underground
CCTV Drainage Survey

AMETHYST SURVEYS LIMITED

Unit 6a Davy Court, Central Park
Rugby, Warwickshire, CV23 0UZ


Tel: 01788 566740
Fax: 01788 571158

Email: enquiries@amethystsurveys.com
www.amethystsurveys.com

DATE: 12.10.20	JOB No: 14230
DRAWING No: 14230_CCTV_3	REV: 0
DRAWN: DOT	SURVEYED: AS
APPROVED: TPD	SCALE: 1:200 @A0



CCTV REPORT



Run No:	5	Weather:	Dry	Duty:	Surface
Start:	MH4	Upstream To	Destination:	Base Bend	
Material:	Vitrified Clay	Shape:	Circular	Pipe size:	100
MH Condition:	Roots	MH Defect:	None	Pre-Cleaned:	No
			Maximum Defect Grade:	2	
Distance	Defect				Grade
0.00	Water Level 0%				0
3.22	Crack Circumferential from 12 O'clock - 12 O'clock				2
3.52	Crack Circumferential at Joint from 12 O'clock - 12 O'clock				2
5.40	Joint Displacement Medium				2
5.40	Material of Drain/Sewer Changes to PVC				0
8.24	Line of Drain/Sewer Deviates Right Quarter Turn				0
8.24	Joint Displacement Medium				2
8.43	Junction at 12 O'clock				0
8.75	Junction at 3 O'clock				0
9.08	Open Joint Medium				2
9.08	Material of Drain/Sewer Changes to Vitrified Clay				0
10.95	Debris / Silt 5%				1
12.30	Base Bend				0
	End				0
	Water Level 0%				0

