

Blackwell Water Consultancy Ltd work



Blackwell Water Consultancy Ltd review summarised in a report with options for remedial work & new treatment plant

Lifted manhole covers to trace roof drainage

Outline assessment of existing plant and discharge ditch

Review of existing pumping station and tanks