# **Mechanical Service Certificate of inspection**

#### Work Order # 31359920

All queries relating to this certificate should be addressed to: Chubb Fire Mechanical, Oak House, Littleton Road, Ashford, Middlesex TW15 1TZ

Tel: 01784 425900 Email: Mechanical@chubb.co.uk

## Site Name and Site Address

#### Hertfordshire Constabulary

Hertfordshire Police HQ, Stanborough Road, , Welwyn Garden City, , AL8 6XF

### Summary of Work performed

PREVENTATIVE MAINTENANCE VISIT 5 x Fire Hydrants tested. All Passed

Work Order Details					
Contract No:	1643858-Standard	System Type:	Fire Alarm		
Visit Date:	24/01/2022	Work Done Code:	WM		
Hours Worked:	2 Hrs 4 Mins	Engineer:	William Nagle		
Customer Order No:	HAN19156				
Complexed Hurite					

#### Serviced Units

Equipment Type	
Hvdrants	

See attached Hydrant Report

Customer Signature				
Customer Name:	Neil Major	Title:	Maintenance	
Customer Signature:	$\times$	Date:	24/01/2022 10:29	
Engineer Signature:		Date:	24/01/2022 10:29	

Terms: Subject to CFS standard published conditions of sale applicable to the goods or services described above, a copy of which can be supplied on request. The inspection or service is carried out in accordance with the relevant standard or to agreed contractual requirements as appropriate, (Hosereel service includes only that equipment from the hose shuts-off nozzles back up to and including the hosereel isolating valve) Customers are reminded that it is their responsibility to carry out regular checks of their fire equipment to ensure that it is not obviously damaged, defective or leaking and that it is visible, unobstructed and readily available for use.

