

Hydrant Test Report



Cert No: 31359920 **Date:** 24/01/2022

Customer Name: Hertfordshire Constabulary


Address:


Hertfordshire Police HQ
Stanborough Road

Welwyn Garden City

AL8 6XF

Equipment Type	Quantity	Correct Sign	Cover Painted Yellow	Flow Pressure KPA/PSI	Flow Rate L/min	Free Drain	Frost Valve Fitted	HYD Type	Location	Outlet No More Than 300mm	Pass	Pit in Good Order	Remarks	Service Completed In Accordance With The Relevant Standards?	Static P/Test (bar)
Hydrants - 1	1	Yes	Yes	.	620	Yes	Yes	Screw	4	Yes	Yes	Yes	.	Yes	4
Hydrants - 2	1	Yes	Yes	.	740	Yes	No	Screw	5	Yes	Yes	Yes	.	Yes	4
Hydrants - 3	1	No	Yes	.	650	Yes	No	Screw	3	Yes	Yes	Yes	.	Yes	4
Hydrants - 4	1	Yes	Yes	.	780	Yes	No	Screw	1	Yes	Yes	Yes	.	Yes	3.5
Hydrants - 5	1	Yes	No	.	860	Yes	No	Screw	2	Yes	Yes	Yes	.	Yes	4

Customer Name: Neil Major **Title:** Maintenance
Customer Signature:  **Date:** 24/01/2022 10:29

Engineer Name: William Nagle **ID:** 50009375
Engineer Signature:  **Date:** 24/01/2022 10:29

