



Pedestrian security gate Site security gate

Disabled car parking

Visitors' car parking Automated barrier

Turning head

Mobile library vehicles parking

Transit van vehicles Service bay

Loading bays

Recycling container

Staff cycle covered parking

Boundary wall / railings

Existing road / parking edge

Proposed security fence Proposed gate

Existing fence

Proposed gabion screen

Staff car parking

Hedge retained

Hedge removed

Trees removed

Trees retained

Trees proposed

vehicular surface within site

PARKING BAYS Staff: 80 (including 5 disabled bays) Visitors: 20 (including 2 disabled bays) Mobile Library Vehicles: 9 Transit Van: 1 Service bays: 1 Loading Bays: 5
Waste/Recycling Container: 1
Bicycles (visitors): 8
Bicycles (staff): 14 sheltered (3 sides +

